United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

. Number

SA8291SW-D

This certificate, issued to

Dassault Falcon Jet P.O. Box 967 Little Rock, Arkansas 72203

certifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Part 25 of the Federal Aviation

Regulations.

Original Product - Trype Certificate Number:

A46EU

Dassault Aviation

Model:

Falcon 900EX

Description of Type Design Change:

Installation of the Battery Installations in accordance with Drawing List Report No. F9EX-01003 Revision F dated 9-14-2000, or later FAA approved revision.

Continued on sheet 2

Limitations and Conditions:

Compatibility of this modification with other previously approved modifications must be determined by the installer.

If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

The F9EX-01003-503 and F9EX-01003-507 installation is limited to aircraft serial number 049.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

March 14, 1997

Date reissued:

Date of issuance:

May 1, 1997

Date amended: 8-22-97, 10-15-99, 9-15-00, 9-23-00 Rev 4

By direction of the Administrator Sough F. Cerke (Signature)

Andrew A. Boersma
DAS8SW COORDINATOR

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

Britte States of America

Department of Transportation—Jederal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number SA8291SW-D

Description of Type Design Change:

FAA Approved Airplane Flight Manual Supplement, Report No. 36558-1, dated 5-1-97, and Airplane Maintenance Manual Supplement, Report No. 36575 dated 6-9-97, or later approved revision is for the F9EX-01003-501 installation.

FAA Approved Airplane Flight Manual Supplement, Report No. 36558-2, dated 10-15-99, and Airplane Maintenance Manual Supplement, Report No. 36722 dated 10-8-99, or later approved revision is for the F9EX-01003-503 installation

FAA Approved Airplane Flight Manual Supplement, Report No. 36558-3, dated 9-23-2000, and Airplane Maintenance Manual Supplement, Report No. 36722 dated 10-8-99, or later approved revision is for the F9EX-01003-505 installation.

FAA Approved Airplane Flight Manual Supplement, Report No. 36558-4, dated 10-15-99, and Airplane Maintenance Manual Supplement, Report No. 36806 dated 9-13-2000, or later approved revision is for the F9EX-01003-507 installation.

INSTRUCTIONS: The transfer endorsement below may be used to notify the appropriate FAA Regional Office of the transfer of this Supplemental Type Certificate.
The FAA will reissue the certificate in the name of the transferee and forward it to him.
TRANSFER ENDORSEMENT
Transfer the ownership of Supplemental Type Certificate Number
to (Name of transferee)
(Address of transferee)(Number and street)
(City, State, and ZIP code)
from (Name of grantor) (Print or type)
(Address of grantor)(Number and street)
(City, State, and ZIP code)
Extent of Authority (if licensing agreement):
Date of Transfer:
Signature of grantor (In ink):